

\*\*\*\*\*  
\*\*\* C17 Sample Program BUG REPORT \*\*\*\*\*  
\*\*\*\*\*  
Registration No. :C17\_003\_SampleProgram  
Issue and revision :2014/10/14

--- <Tool name / Object version> -----  
S1C17600 Series  
\* S1C17653/651 Sample program rev1.0

--- <Content> -----  
Header file includes partial description errors on registers of WDT\_ST,  
T16A\_CCCTL0, VD1\_CTL, and bit of UART\_STO\_TDBE, so they can't be used  
appropriately.

--- <Generation condition> -----  
When these registers and the bit are used with the header file.

---- <Temporary Measures> -----  
Replace c17651\_653\_reg.h and reg folder in the Sample program with  
corresponding file and folder in S1C17651\_653 header file rev1.1.

--- <About the correction version> -----  
The following corrected version is released.  
\* S1C17651\_653 Header file rev1.1