

C17\_002\_SampleProgram\_e.txt

\*\*\*\*\*  
\*\*\* C17 Sample Program BUG REPORT \*\*\*\*\*  
\*\*\*\*\*

Registration No. :C17\_001\_SampleProgram  
Issue and revision :2010/07/20

--- <Tool name / Object version> -----  
Common  
\* Flash Protection Ver1.0

--- <Content> -----  
GDB on GNU17 can not recognize the comment parts on command file because of using  
[REM] instead of [#] on the command file.

--- <Generation condition> -----  
It fails using the application note and bat file with command file.

---- <Temporary Measures> -----  
Change the comment parts of command file as [REM] to [#].  
Or replace the GNU17 ver2.0.0. (GNU17 ver2.0.0 or after version includes this function)

--- <About the correction version> -----  
Each program as follows is updated.  
\* Flash Protection Ver1.1